
KEY NOTES

- (12) Existing MB or Smooth BUR
- (14) Existing Structural Deck and Insulation Assembly
- (19) Existing Wall Assembly
- 47 Geogard Seam Sealer
- 62 Permafab
- $\langle 78 \rangle$ Alumanation 301



Alumanation 301 Restoration Detail, MB or Smooth BUR, Through-Wall Scupper Detail 19232

